


Probler P2 Gun

Air Passage Locations



The set screws on the gun all represent air passages as shown in the above diagram.

All air passage ways must be completely free of debris and cleaned with the proper Sized drill bits.

If any one of these passages are partially blocked or completely blocked it can and will effect the function of the gun.