

August 25, 2006

**For Immediate Release**

**This service bulletin is for the Hydraulic drive urethane equipment; MH2 and MH3.**

**The overpressure switch, #21830-00 has been relocated.**

Previous production models have the overpressure switch located at the gauge manifold on the front of the machine, where the main hose connects to the equipment. A product improvement has been made by moving these switches to the outlet port of the main proportioner pump. The relocation improves performance of the switch and increased reliability.

The switch part # number and field service of the switch has not changed.

**This service bulletin is effective immediately.**