



You must start your pull on the string line and keep the angle of pull the same at all times in order to keep a straight cut line at the proper angle.

Approximate angle to pull at.

At this angle the material will be cut off at about a 22 Degree angle.