


# 22530-00 DRUM MIXER



## NOTE:

\*A) Gap setting between Air Motor Drive End Bell and Mixer Coupling, P/N 22531-00 is .125".

\*B) Gap Setting between Drum Material Mix Adapter, P/N 22532-00 and Stop Collar, P/N 22535-00 is .125".

## REPAIR KIT: K202\*

(\*) Used for Air Motor P/N 22537-00